

Outage periods of 400kV of overhead transmissions lines - 2024

Overhead line	January	February	March	April	May	June	July	August	September	October	November	December	Comments
V404			18- -18 26- -26						16- -20 29- -29			1- -30	
V405										7- -11			
V406					27- -31								
V407						10- -14							
V408						3- -6							
V409			18- -22										
V410			25- -28										
V424						3- -7							
V425									30-	-4			
V426											4- -8		
V427											11- -15		
V428								5-	-1				
V429										14- -18			
V439									2- -6				
V440						3- -7				28- -31			
V447						10- -14							
V448					6- -10					7- -11			
V449						15- -16	22-	-16					
V461			4- -28							14- -31			
V477				3-	-21	7- -9 14- -15							
V478				3-	-21								
V479					13- -24								
V480										21- -31			
V481									23- -27				
V483				15- -26									
V484				29-	-10								
V487									2- -6				
V488									9- -13				
V489									16- -20				
V490					27- -31								
V491									9- -13				
V492				8- -12									
V493									23- -27				
V494							29-	-2					
V495						16- -20							
V496						21-	-26						
V497							29-	-2					
V498								19- -30					
V043						21-	-26						
V044					6- -24								
V045									11- -12				
V046				8- -19									
V047									9- -20				
V048				8-	-3								
V049													
V050					6- -14								
V051													
V052													

Outage periods of 220kV of overhead transmissions lines - 2024

Overhead line	January	February	March	April	May	June	July	August	September	October	November	December	Comments
V270								6- -15					
V271										14- -25			
V273							8- -12						
V274													
V275													
V279									16- -20				
V280													
V281						17- -21							
V282						24- -28							
V283													
V071		5- -9				7- -8 14- -15							
V072			11-	-15									

Maintenance of the power transformers - 2024

Transformer	January	February	March	April	May	June	July	August	September	October	November	December	Comments
T401 KRIZ													
T401 LEME						7- -8 14- -15					4- -8		
T401 SUCA								19- -23	2- -6				
T401 BOSA										7- -10			
T402 BOSA	8-		-28										
T401 BYST									9- -13				
T402 BYST									16- -20				
T401 GABC					10- -19								
T401 HZDA				22- -26									
T402 HZDA							8- -12						
T403 HZDA					27- -31								
T402 KRIZ											11- -13		
T403 KRIZ											14- -16		
T401 KOSI									9- -13				
T402 KOSI									16- -20				
T402 LEME						7- -8 17- -21 14- -15							
T403 LEME						24- -28							
T403 LEME						24- -28							
T401 LEVI								5- -9					
T403 LEVI								12- -16					
T401 LMAR							29-	-2					
T402 LMAR								26- -30					
T401 MEDZ						10- -14			30-	-4			
T402 MEDZ													
T401 MOLD									23- -27				
T402 BISK				6- -7	20-							-16	
T403 BISK	29- -31	20- -22 28-	-1	3-	-9								
T404 BISK			27- -28										
T402 RSOB				29-	-3								
T403 RSOB					6- -10								
T401 SNV								1- -5					
T402 SNV								22- -26					
T401 STUP			23- -24										
T402 STUP			25- -26										
T401 VARI				15- -19									
T401 VOLA										14- -18			
T402 VOLA										21- -25			
T201 BYST													
T202 BYST													
T202 KRIZ													
T201 LEME							15- -19						
T201 PBYS					13- -17								
T202 PBYS					20- -24								
T201 SALA									16- -20				
T201 SENI													
T201 SUCA						3- -7		19- -23	2- -6				

